
PROJECT: OVERCOAT

Steve Schirber 612-787-5716 steve@cocoon-solutions.com



Discussion Plan

- 1. Purpose of Project Overcoat
- 2. Current Story and a Half Methods
- 3. Project Overcoat Case Studies
- 4.Findings

Purpose

- 1. Solution to Ice dams and related problems associated with Story and half Homes
- 2. Test the Exterior Thermal Moisture
 Management System (ETMMS) as a roof only approach roof-only approach for maximizing opportunities for insulation, air sealing, and roof deck ventilation
- 3. Compare the ETTMS Approach to current methods

What is a Story and a Half (SAAH)?











Why Story and a Half

- 1. Represents common building type
- 2. Typically has performance issues
- 3. Difficult to retrofit

What are the problems with the Story and a Half?

- 1. Durability
- 2.Ice Dams
- 3.Comfort
- 4. Air Quality
- 5. Moisture Issues
- **6.Utility Costs**

WHY ARE SAAH'S A PROBLEM?

Why are SAAHs a Problem?

Boundary Conditions!

Why are SAAHs a Problem?

- 1. Attics are not intended to be finished
- 2. Desire to maximize space
- 3. Using the roof for a wall
- 4. Creating confused spaces
- 5. The devil is in the details

Retrofit Performance Goals

- 1. Air Leakage reduction
- 2. Moisture Management
- 3.Increase R-Value
- 4. Minimize Thermal Bridging
- 5. Appropriate Ventilation(IAQ)
- 6.Combustion Safety

Current Methods: Interior Approach













Interior Approach EXISTING CONDITION




Interior Approach EXISTING CONDITION




ROOF VENTILATION




ROOF VENTILATION




ROOF VENTILATION




CAVITY INSULATION




Interior Approach CAVITY INSULATION



FOAM SHEATHING



FOAM SHEATHING



Current Methods: Mixed Interior/Exterior Approach



















































































Overcoat: Case 1




































1. Identify areas affected by elevating roof deck 6"







- 1. Identify areas affected by elevating roof deck 6"
- 2. Eliminate roof penetrations



- 1. Identify areas affected by elevating roof deck 6"
- 2. Eliminate roof penetrations
- 3. Sequence Tear off and Dry-in



Remove Existing Attic Insulation




Demo





Demo

















Air Test!





Insulation Details



Insulation Details



New Soffit/Eave Detail



New Soffit/Eave Detail



Insulation



Insulation



Insulation



Frame Venting Sleepers



Frame Venting Sleepers



Frame Venting Sleepers











Roofing




Roofing



Roofing



Finished!



Finished!



Final Testing

Final Testing



Results

Overcoat: Case 1

MEASUREMENT	PRE TEST	POST TEST			REDUCTION	
Air Leakage (CFM50)	2371	-	1880	= 1	491	CFM50
Air Changes (ACH50)	4.93	-	3.9	-	1.0	ACH50



Existing House





Existing House





Existing Upper Level






Existing Insulation





Demo



Demo



Demo





Membrane





Membrane




Membrane



Air Test





Air Test Again!



Framing New Soffit/Eave Detail



Framing New Soffit/Eave Detail













Frame Gable Rakes



Frame Gable Rakes



Frame Venting Sleepers



Frame Venting Sleepers



Roofing





Roofing



Roofing




Finished!



Finished!



Finished!



Results

Overcoat: Case 2

MEASUREMENT	PRE TEST	POST TEST	REDUCTION	% REDUCTION
Air Leakage (CFM50)	2925 CFM	1289 CFM	1636 CFM	56%
Air Changes (ACH50)	7.02	3.09	3.93 ACH	56%


RESULTS

- 1. Thermal imaging done in conjunction with blower doors suggests very effective air sealing method
- 2. Eliminated ice dam formation (as a result of heat loss)
- 3. Occupants reported significant comfort changes
- 4. Comparative effectiveness for air leakage is not readily available without knowing percent of leakage from treated surface area
- 5. Assume equal leakage per square foot of surface area

CANDIDATE FOR OVERLAY

- 1. Finished attic space
- 2. House has heat loss performance issues
- 3. Needs new roof
- 4. Needs Eave and Cornice work
- 5. Client can afford it!

THANK YOU!



Steve Schirber 612-787-5716 steve@cocoon-solutions.com

